

FIG.1

FIG.2

OUTPUT FACTOR	
INPUT (W)	(WITHOUT PISTON SPRING)/(WITH PISTON SPRING)
60	0. 983
80	0. 976
100	0. 970

FIG.3





FIG.4






FIG.